


# TS Steel

Manual 09052009a

## All Steel Snouts

1. Attach the sensor to the mounting bracket as shown.



2. Determine mounting location.
  - Slide sensor assembly into snout as far forward as possible.
    - This may require removing material from the lower surface of the snout.
  - Mark the hole locations.
3. Adjust sensor height.
  - The sensor should be as far into the snout as possible without causing the arms to rub the bottom of the snout.
4. Fasten bracket to snout using provided self-tapping screws.

**HEADSIGHT INC.**  
HARVESTING SOLUTIONS



5. Install bubble shield using provided screws.



## Crop sensor mounting kit



- |     |          |                           |
|-----|----------|---------------------------|
| 1-  | B2721    | -Mounting kit complete    |
| 1-  | HT2721   | -Bracket                  |
| 4-  | 08200102 | -Screws                   |
| 2-  | 08200134 | -Bolt Flange 5/16" x .75" |
| 2-  | 08200133 | -Washer 5/16"             |
| 1-  | HT2694   | -bubble tip (not shown)   |
| AR- | 08200107 | -Screws                   |
| AR- | 08100101 | -Cable clamp small        |
| AR- | 08100102 | -Cable clamp large        |
| AR- | 08300102 | -Zip ties                 |